

MARBLE DRY RESURFACE AND POLISHING PROCEDURES

Step 1—Scratch Removal Dry Method

Thoroughly strip the floor to re-move all surface coatings.



Hone the marble with **New Dimensions Foam Disc Holder & Scratch Removal Discs** and water.



Honing process time: Marble - 30 seconds per sq. ft. Keep Wet at all time.



Vacuum the slurry and rinse with **New Dimensions Neutral Stone Cleaner**.



Step 2— Marble Dry Polishing (Maintenance Procedures)

Mix 1 oz Dry Polish Powder with 3 oz water.



Stir the mixture well.



Pour 1 oz. mixture onto floor to polish 10 to 12 sq. feet.



Buff to dry with a white polishing pad. **Do not add water during the process.**



Repeat application if higher gloss is desired

- Protect with New Dimensions Stone Impregnator Seal
- Clean daily with New Dimensions Neutral Stone Wash
- Maintain gloss with New Dimensions Marble Gloss

